



CROSS SECT. THRU RDWY.

(LOOKING




RUPTURED VOID REPAIR




SECTION THRU PARAPET ON BRIDGE

UNDER THE BID ITEM "MASONRY ANCHORS TYPE S". ANCHORED REINFORCING STEEL SHALL BE PAID FOR SEPARATELY AS PROVIDED IN SECTION 505 OF THE STANDARD SPECIFICATIONS FOR BAR STEEL REINFORCEMENT.



SECTION THRU PARAPET ON WING



ASPHALTIC OVERLAY

CONCRETE OVERLAY

